

# Houston Lighting & Power Company

Electric Tower  
P.O. Box 1700  
Houston, Texas 77001

July 11, 1979

ST-HL-AE-361  
SFN: C-0570

Mr. W. C. Seidle, Chief  
Reactor Construction & Engineering  
Support Branch  
U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, TX 76012

SUBJECT: RESPONSE TO NRC INSPECTION FINDINGS  
SOUTH TEXAS PROJECT ELECTRIC GENERATING STATION  
DOCKET NOS. 50-498/79-08 AND 50-499/79-08

Dear Mr. Seidle:

The following is our response to the items of noncompliance identified in IE Inspection Report Nos. 50-498/79-08 and 50-499/79-08 dated June 4, 1979.

Failure to Have A Procedure for Monitoring Welding Operations

1. Corrective Action Taken

A written procedure has been issued to document the weld monitoring program for containment liner and reactor coolant system support welding.

2. Recurrence Control

The failure to provide a written procedure to document the weld monitoring program stems from a difference in interpretation of requirements. Procedures to control activities affecting quality will be written and issued as needed.

284358

7909210/36


Mr. W. C. Seidle

Page 2

July 11, 1979

The completion of corrective action and recurrence control was achieved on June 19, 1979.

Very truly yours,



E. A. Turner, Vice President  
Power Plant Construction  
& Technical Services

EAT:jow

cc: Messrs. G. W. Oprea, Jr.  
R. A. Frazar  
D. G. Barker  
M. L. Borchelt (CPL)  
J. W. Moore (CPL)  
J. B. Poston (CPS)  
R. C. Mecke (CPS)  
R. L. Hancock (COA)  
H. L. Peterson (COA)  
T. D. Stanley  
G. B. Painter  
M. B. Schwarz (Baker & Botts)  
H. O. Kirkland (B&R)  
H. C. Dodd (B&R)  
C. W. Vincent (B&R)

STP RMS

284359