

Wainick
cc: Sirbu

AMERICAN ELECTRIC POWER Service Corporation



2 Broadway, New York, N. Y. 10004
(212) 422-4800

JOHN E. DOLAN
Senior Executive Vice President
Engineering

May 16, 1978

Donald C. Cook Nuclear Plant Unit No. 2
Docket No. 50-316
License No. DPR-74

Mr. J. G. Keppler, Regional Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

This letter provides the written followup report to our verbal report made to NRC Region III Inspector, Mr. K. R. Baker on May 3, 1978, which was also confirmed by letter from Mr. D. V. Shaller to you on May 3, 1978. At that time we reported that when Unit No. 2 entered Mode 4, the Containment Spray Pump switches were not in the automatic standby position as required by Technical Specification 3.6.2.1. The attached enclosure is submitted in fulfillment of the requirement of Technical Specification 6.9.1.8 to provide prompt notification with written followup for an event of this nature.

Very truly yours,

John E. Dolan
John E. Dolan

JED:clb
Enclosure

cc: R. C. Callen
G. Charnoff
P. W. Steketee
R. J. Vollen
R. Walsh
R. W. Jurgensen
D. V. Shaller - Bridgman

79092104 7.7

79092104 7.7

990030

MAY 23 1978