



ARKANSAS POWER & LIGHT COMPANY
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

September 14, 1979

1-099-13

Mr. K. V. Seyfrit, Director
Office of Inspection & Enforcement
Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Subject: Arkansas Nuclear One - Unit 1
Docket No. 50-313
License No. DPR-51
Reportable Occurrence Report
Nos. 50-313/79-015 and
50-313/79-016
(File: 0520)

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 1 Technical Specification 6.12.3.2, we have attached the subject reports concerning a monthly surveillance operational test which resulted in Diesel Generator #2 tripping due to low oil pressure (50-313/79-016).

As requested in IE Bulletin 79-02, an analysis of Seismic Category I pipe supports for baseplate flexibility revealed 37 restraints were identified as having a safety factor of less than two (50-313/79-015).

Very truly yours,

David C. Trimble
for David C. Trimble
Manager, Licensing

DCT:REI:vb

Attachment

cc: Mr. Victor Stello, Jr., Director
Office of Inspection and
Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. W. D. Johnson
U. S. Nuclear Regulatory Comm.
P. O. Box 2090
Russellville, AR 72801

Mr. Norman Haller, Director
Office of Management and Program Analysis
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

1038 325

Aug 25/11