

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

September 10, 1979

TELEPHONE AREA 704  
373-4082


Mr. J. P. O'Reilly, Director  
U.S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, GA 30303

Re: Catawba Nuclear Station  
RII:RJH  
Inspection Reports: 50-413/79-12 and 50-414/79-12

Dear Mr. O'Reilly:

In his August 15, 1979 letter, Mr. C. E. Murphy of your office requested that Duke Power Company make a response supplementing our August 6, 1979 submittal concerning the above referenced Inspection Reports. Attached is Duke's supplemental response.

Very truly yours,



William O. Parker, Jr.

ROS/sch

Attachment



7910050055

1109 087

790124  
OFFICIAL COPY

DUKE SUPPLEMENTAL RESPONSE TO  
DEFICNEICY SO-413 & 414/79-12-02

QAP PROCEDURE P-1

Below is Duke's supplemental response to each generic example cited by Mr. R. J. Hardwick in Deficiency SO-413 & 414/79-12-02, concerning QAP Procedure P-1.

1. A sample of approved documentation has been reviewed as an indicator to see if a generic problem exists. No significant discrepancies were identified.
2. Approved documents which were placed in QC hold and required QA Engineering and Service approval will be reviewed. Clarifications will be made on documents which have QA program deficiencies. Full compliance will be achieved by October 1, 1979.

1109 088