



**Wisconsin Electric** POWER COMPANY  
231 W. MICHIGAN, P.O. BOX 2046, MILWAUKEE, WI 53201

October 10, 1979

Mr. J. G. Keppler, Regional Director  
Office of Inspection and Enforcement,  
Region III  
U. S. NUCLEAR REGULATORY COMMISSION  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

DOCKET NO. 50-301  
POINT BEACH NUCLEAR PLANT UNIT 2  
LICENSEE EVENT REPORT NO. 79-007/01T-0

Enclosed is Licensee Event Report No. 79-007/01T-0 (a 14-day follow-up report) with an attachment which provides a description of an event reportable in accordance with Technical Specification 15.6.9.2.A.9, "Performance of structures, systems, or components that requires remedial action or corrective measures to prevent operation in a manner less conservative than that assumed in the accident analyses, in the safety analysis report, or technical specifications bases; or discovery during plant life of conditions not specifically considered in the safety analysis report or technical specifications that require remedial action or corrective measures to prevent the existence or development of an unsafe condition."

Very truly yours,

C. W. Fay, Director  
Nuclear Power Department

Enclosure

OCT 12 1979

7910190417

1173 352

Acc 2  
S. 11