

1
TENNESSEE VALLEY AUTHORITY

USNRC
CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

79 OCT 3 P2:02

October 1, 1979

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303


Dear Mr. O'Reilly:

HARTSVILLE AND PHIPPS BEND NUCLEAR PLANTS ALL UNITS - REPORTABLE
DEFICIENCY - UNACCEPTABLE BENDING OF WELDED STUD ANCHORS ON
EMBEDDED PLATES (NCR'S HNP-A-064 AND PBNP-039)

Initial report of the subject deficiency was made to W. B. Swan, NRC-OIE, Region II, on August 30, 1979, for the Hartsville Nuclear Plant and on August 31, 1979, for the Phipps Bend Nuclear Plant. In compliance with paragraph 50.55(e) of 10 CFR Part 50, we are enclosing the first interim report of the subject deficiency. We anticipate transmitting another report to NRC-OIE on or before June 1, 1980. If you have any questions regarding this matter, please call Tish Jenkins at FTS 854-2014.

Very truly yours,

TENNESSEE VALLEY AUTHORITY



L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Director (Enclosure)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

1174 274

B019
S.1/81