

NRC DISTRIBUTION FOR RT 50 DOCKET MATERIAL

50-289

FILE NUMBER

INCIDENT REPORT

TO: J.P. O'Reilly

FROM: Metropolitan Edison Co.
Reading, PA

DATE OF DOCUMENT

6-18-76

DATE RECEIVED

7-8-76

☒ LETTER☐ NOTORIZED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

☐ ORIGINAL☒ UNCLASSIFIED☒ COPY

1

DESCRIPTION

Ltr. providing R.O. # 76-24/1T, on 6-18-76,
Concerning Improper incorporation of fuel
densification penalty.....
(1 Carbon Signed Cy. Received)
(1 Page)

ENCLOSURE

ACKNOWLEDGED

DO NOT REMOVE

POOR ORIGINAL

PLANT NAME: Three Mile Island # 1

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

SAFETY

FOR ACTION/INFORMATION

ENVIRO

SAB 7-10-76

BRANCH CHIEF:

Reid

W/3 CYS FOR ACTION

LIC. ASST:

Ingram

W/ CYS

ACRS16 CYS ~~XXXXXXXX~~ SENT TO LA

INTERNAL DISTRIBUTION

REG FILE

NRC PDR

I & E (2)

MIPC (3)

SCHROEDER/IPPOLITO

HOUSTON

NOVAK/CHECK

GRIMES/

CASE

Butler

HANAUER

TEDESCO/MACCARY

EISENHUT

BAER

SHAO

VOLLMER/BUNCH

KREGER/J. COLLINS

Denise

EXTERNAL DISTRIBUTION

LPDR: Harrisburg, Pa.

TIC

NSIC

CONTROL NUMBER

1490 010

6747

7910240

847



METROPOLITAN EDISON COMPANY

SUBSIDIARY OF GENERAL PUBLIC UTILITIES CORPORATION

POST OFFICE BOX 542 READING, PENNSYLVANIA 19603

TELEPHONE 215 - 929-3601

June 18, 1976

GQL 0890

Mr. J. P. O'Reilly, Director
Office of Inspection & Enforcement, Region 1
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA. 19406



Dear Sir:

Docket No. 50-289
Operating License No. DPR-50

In accordance with the Technical Specifications of our Three Mile Island Nuclear Station Unit 1 (TMI-1), we are reporting the following reportable occurrence.

- (1) Report Number: ER 76-24/1T
- (2a) Report Date: June 18, 1976
- (2b) Event Date: June 4, 1976
- (3) Facility: Three Mile Island Nuclear Station Unit 1
- (4) Identification of Event:

Title: Improper incorporation of fuel densification penalty into cycle 2 technical specifications, which affect figures 2.1-1, 2.1-3 and 2.3-1.

Type: A reportable occurrence as defined in Technical Specification 6.9.2.A(8) in that this error in an analysis described in the basis for Technical Specifications might have permitted reactor operation in a manner less conservative than assured in the safety analyses.

1490 011

6747