



METROPOLITAN EDISON COMPANY SUBSIDIARY OF GENERAL PUBLIC UTILITIES CORPORATION

POST OFFICE BOX 480 MIDDLETOWN, PENNSYLVANIA 17057

TELEPHONE 717-644-4041

August 21, 1975

Mr. J.P. O'Reilly, Director
Directorate of Regulatory
Region I
631 Park Avenue
King of Prussia, Pa. 19405

POOR ORIGINAL

Operating License DPR-50
Docket 50-289

Subject: Abnormal Occurrence No. AD 75-27

Dear Mr. O'Reilly:

This telegram is to confirm the telecon between Lee Spessard (Region I-NRC), and J.J. Colitz (TNI Unit 1 Superintendent) at 1430 hours 21 August 1975.

The following report is submitted in accordance with paragraph 6.7.2.a.2 (page 6-11) of the Technical Specifications.

On August 21, 1975, during a routine inspection of the Auxiliary Building, a pin hole leak was found in the socket weld joint where the A Makeup Pump suction line vent connects to the pump suction header. This is considered an Abnormal Occurrence degradation of a boundary designed to contain radioactive liquid.

The leak is being repaired and a hydroslater test will be performed following weld repair of the vent line.

An investigation is being conducted into the reasons for recurring failure in the vent line to header connection weld. On completion of the investigation appropriate corrective action will be initiated.

Very truly yours,

J.J. Colitz

J.J. Colitz
Unit 1 Superintendent

JJC/dm

1476 188

7910240 912