

NRC FORM 195
(2-76)

U.S. NUCLEAR REGULATORY

MISSION

DOCKET NUMBER

50-289

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER

TO: R W Reid

FROM: Metropolitan Edison Co
Reading, Pa
J G HerbeinDATE OF DOCUMENT
9-9-77DATE RECEIVED
9-13-77☒ LETTER
☒ ORIGINAL
☐ COPY☐ NOTORIZED
☒ UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

1 Signed

DESCRIPTION

ENCLOSURE

Notification of tech specs violation
in that inservice tendon surveillance
program was not completed on time
& advising that program will be
completed by 10-7-77.

ACKNOWLEDGED

1p

DO NOT REMOVE

PLANT NAME: Three Mile Island #1

9-13-77 ehf

1491 162

SAFETY

FOR ACTION/INFORMATION

BRANCH CHIEF: (7)

Reid

INTERNAL DISTRIBUTION

REG FILE

NRC PER

I & E (2)

OELD

HANAUER

CHECK

STELLO

EISENHUT

SHAO

BAER

BUTLER

GRIMES

J. COLLINS

EXTERNAL DISTRIBUTION

CONTROL NUMBER

LPDR: HARRISBURG, PA.

TIC

NSIC

16 CYS ACRS SENT CATEGORY

B

772560064

7910800535 P



METROPOLITAN EDISON COMPANY SUBSIDIARY OF GENERAL PUBLIC UTILITIES CORPORATION

POST OFFICE BOX 542 READING, PENNSYLVANIA 19603


TELEPHONE 215 - 929-3601

September 9, 1977
GQL 1238

Director of Nuclear Reactor Regulations
Attn: R. W. Reid, Chief
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Sir:

Regulatory



13,
pdk

Three Mile Island Nuclear Station, Unit 1
Operating License No. DPR-50
Docket No. 50-289

The purpose of this letter is to inform your office of a situation which could be considered as not having met the requirements of TMI-1 Technical Specification 4.4.2.1. "Inservice Tendon Surveillance Program".

More specifically, please be advised that (a) because the Structural Integrity Test was completed on March 10, 1974, we consider the latest required completion date for the current Inservice Tendon Surveillance Program to be September 10, 1977 (i.e., three years from March 10, 1974, plus an allowed 25% variance), and (b) we currently anticipate completing the surveillance program by October 7, 1977.

There are several factors which have caused the contractor delays in completing the surveillance consisting primarily of (a) difficulty in securing an additional ram to perform the testing and problems with the mechanical reliability of the existing ram, (b) difficulty in securing spare parts, such as gaskets for each assembly cover, necessary to complete the surveillance, and (c) time lost due to pickets and inclement weather.

Sincerely,

J. G. Herbein
J. G. Herbein
Vice President

JGH:DCM:iem

1491 163

772560064