

Politan Edison Company
g, Pennsylvania 19603
c Cox

DATE OF DOCUMENT:

12-3-71

DATE RECEIVED

12-6-71

NO.:

202

LTR.

MEMO:

EPORT:

OTHER:

x notarized 12-3-71

ORIG.:

CC:

OTHER:

3 signed

ACTION NECESSARY ☐

CONCURRENCE ☐

DATE ANSWERED:

NO ACTION NECESSARY ☐

COMMENT ☐

BY:

Mr. Morris

CLASSIF:

U

POST OFFICE

REG. NO:

FILE CODE:

50-289

DESCRIPTION: (Must Be Unclassified)

Ltr notarized 12-3-71 trans the
following in response to meeting
W/DRL on 11-3-71:

ENCLOSURES:

"Report on Containment Building Ring
Girder Construction and Repair". See
Rpts. Section

(50 cys rec'd)

REMARKS:

REFERRED TO

DATE

RECEIVED BY

DATE

Long
W/4 cys for ACTION

12-6-71

DO NOT DELIVER

DISTRIBUTION:

Reg Files

AEC PDR

Compliance(2)

OCC, Rm P 506A

Dube/Wilson

DeYoung

Kleckhr

Denton

Dromerick

Lange (2)

Pawlicki

Minogue

Moore

Rosen

Collins

Thompson

DTIE(Laughlin)

NSIC(Buchanan)

ASLR(Yore "H" St)

Warren Nyer(2)

Chief Water Reactors

Case(Mail Control)

202

U.S. ATOMIC ENERGY COMMISSION

MAIL CONTROL FORM FORM AEC-3265
(8-60)

☆ U.S. GOVERNMENT PRINTING OFFICE: 1970-406-979

POOR ORIGINAL

1584 248

7911070 681

A

METROPOLITAN EDISON COMPANY

Subsidiary of General Public Utilities Corporation

P. O. Box 542

READING, PENNSYLVANIA 19603



FREDERIC COX
PRESIDENT

December 3, 1971

Dr. Peter A. Morris, Director
Division of Reactor Licensing
U. S. Atomic Energy Commission
Washington, D. C. 20545

Re: Docket No. 50-289
Three Mile Island Nuclear
Station - Unit 1

Dear Dr. Morris:

Enclosed please find fifty (50) copies of a summary report entitled "Report on Containment Building Ring Girder Construction and Repair". This report was prepared as a result of a meeting on this subject held with members of your staff on November 3, 1971.


The report describes an unsatisfactory condition that resulted during fabrication of the Containment Building ring girder for Unit 1 of the Three Mile Island Nuclear Station. It also sets forth the corrective action that is being taken and presents an analysis that shows that the final installation will meet the original design criteria for the ring girder.

It should be noted that there have been two changes in the program that was described during the November 3rd meeting. They are:

1. The application of an acceptance criteria for partially damaged reinforcing bar (see Section #4.01.2 of the report).
2. The possible use of a butt welding technique for reinforcing bar replacement (see Section #4.02.2 of the report).


As indicated in the report, the repair process is underway. However, the pouring of replacement concrete, which could bury repaired reinforcing bars and conduit, will not begin before December 15, 1971.

Very truly yours,


Frederic Cox

1584 249

mel
attachments



5232

A circular postmark from the U.S. Atomic Energy Commission. The outer ring contains numbers 1 through 12. The word "RECEIVED" is arched across the top. The date "DEC 6 1971" is stamped in the center, with a small arrow pointing to the right. Below the date, the text "U.S. ATOMIC ENERGY COMMISSION" and "Regulatory Mail Service" is printed.

- 5232