

PHILADELPHIA ELECTRIC COMPANY

2301 MARKET STREET

P.O. BOX 8699

PHILADELPHIA, PA. 19101

(215) 841-4000

November 2, 1979

Mr. Boyce H. Grier, Director  
Office of Inspection & Enforcement  
Region I  
United States Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406


Dear Mr. Grier:

The following occurrence was reported to Mr. Greenman,  
Region I, Office of Inspection and Enforcement on October 19, 1979.

|                  |   |
|------------------|---|
| Reference:       | Docket No. 50-278   |
| Report No.:      | LER 3-79-29/1P-0  |
| Occurrence Date: | October 19, 1979  |
| Facility:        | Peach Bottom Atomic Power Station<br>R. D. 1, Delta, PA 17314 |

Subsequent to the prompt response on October 19, 1979,  
it was determined by the Plant Operations Review Committee that  
the damaged sway strut on the Unit 3 "C" Reactor Feed Pump  
discharge line was not a reportable occurrence pursuant to the  
Peach Bottom Technical Specifications. The sway strut has,  
however, been replaced. The purpose of this letter is to close  
LER 3-79-29/1P-0.

Very truly yours,

  
M. J. Cooney  
Superintendent  
Generation Division - Nuclear

cc: Director, NRC - Office of Inspection and Enforcement  
Mr. Norman M. Haller, NRC - Office of Management & Program  
Analysis

1329 163

7911140

213

FS