

USNRC REGION II
ATLANTA, GA

TELECOPY

19 OCT 30 P 2: 07

October 29, 1979

Mr. J. P. O'Reilly, Director
USNRC Region II
Office of Inspection & Enforcement
101 Marietta St., Suite 3100
Atlanta, GA 30303

POOR ORIGINAL

RE: Docket 50-302
License DPR-72

This will confirm a report to Mr. D. R. Quick of your office at 1412 on 26 October 1979. It was discovered at 1412 on 26 October 1979 that the pipe stress of a 3 x 2 reducer on the SW system outlet of RCP-1A motor thrust bearing cooler exceeds the FSAR required allowable stress.

Automatic isolation valves are available to isolate the affected section of this line from the SW system.

An engineering evaluation of this event is being conducted to provide a solution to this problem.

A detailed report of this event will follow within fourteen (14) days.

[Signature]
Guy P. Beatty, Jr.
Nuclear Plant Manager
Crystal River Unit #3
Florida Power Corporation

/rc

E. P. O'REILLY
E. M. UPRIGHT
R. D. CHENDEMI
S. A. KENNA
E. L. LONG
A. E. MURPHY
E. T. SUTHERLAND
E. M. CLARK

Verified by

AS, ID

1362 341

7911200 466