



Wisconsin Electric POWER COMPANY
231 W. MICHIGAN, P.O. BOX 2046, MILWAUKEE, WI 53201

DSB

November 16, 1979

Mr. J. G. Keppler, Regional Director
Office of Inspection and Enforcement,
Region III
U. S. NUCLEAR REGULATORY COMMISSION
799 Roosevelt Road
Glen Ellyn, Illinois 60137


Dear Mr. Keppler:

DOCKET NO. 50-266
POINT BEACH NUCLEAR PLANT UNIT 1
LICENSEE EVENT REPORT NO. 79-017/01T-0

Enclosed is Licensee Event Report No. 79-017/01T-0 (a 14-day followup report) with an attachment which provides a description of an event reportable in accordance with Technical Specification 15.6.9.2.A.3, "Abnormal degradation discovered in fuel cladding, reactor coolant pressure boundary, or primary containment."

We will provide you with an additional summary report including the results of our investigations of the tube samples which were removed for metallurgical analysis upon completion of our review of this data. This matter will be the subject of a meeting with representatives of the Office of Nuclear Reactor Regulation in Bethesda, Maryland, on November 20, 1979.

Very truly yours,


Executive Vice President

Sol Burstein

Enclosure

NOV 19 1979

1437 323

7911300551

Acc 2
5/11