

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 C 0 F S V 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 2 0 4 5

LICENSEE CODE

LICENSE NUMBER

LICENSE TYPE

CAT 58

CON'T

01 L 6 0 5 0 0 0 2 6 7 7 1 0 1 7 7 9 8 9

REPORT SOURCE

DOCKET NUMBER

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

02 On October 17, 1979, while operating at 5% reactor power, System 21 Loop 1 surge tank
03 level decreased to the low level trip setpoint which tripped the Loop 1 bearing water
04 pumps, making Loop 1 circulators inoperable per Fort St. Vrain Technical Specification
05 LCO 4.2.1. This is reportable per Fort St. Vrain Technical Specification AC
06 7.5.2(b)3. No accompanying occurrence. No effect on public health or safety.
07
08

09 C B 11 D 12 Z 13 P U M P X X 14 B 15 Z 16
17 7 9 0 5 1 0 3 L 0
18 Z 19 C 20 Z 21 0 0 2 4 Y 23 N 24 N 25 26

LER/RO REPORT NUMBER

EVENT YEAR

SEQUENTIAL REPORT NO.

OCCURRENCE CODE

REPORT TYPE

REVISION NO.

ACTION TAKEN

FUTURE ACTION

EFFECT ON PLANT

SHUTDOWN METHOD

HOURS

ATTACHMENT SUBMITTED

NPRD-4 FORM SUB.

PRIME COMP. SUPPLIER

COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

10 Procedure inadequacy allowed intermittent operation of the bearing water makeup
11 supply and resulted in low surge tank level. The operator did not follow the recom-
12 mended operator action which allowed the loop shutdown to occur. Procedure changed
13 to prevent this situation and operator reinstructed in proper response to alarms.
14

15 C 28 0 0 5 29 N/A 30 A 31 Loop 1 Circulator Shutdown 32
16 Z 33 Z 34 N/A 35 N/A 36
17 0 0 0 37 Z 38 N/A 39
18 0 0 0 40 N/A 41
19 Z 42 N/A 43
20 N 44 N/A 45

NAME OF PREPARER

J. W. Gahm

PHONE: (303) 785-2253

1472 556

291204 0341

NRC USE ONLY