

0-9 947-926

Facility: BSEP Unit No. 2

Event Date: 11-10-79

fit. The scuffing on the stem and bushing was cleaned and the surfaces were polished smooth. The valve was reassembled, the setpoint established, and the valve was tested satisfactorily. This is considered an isolated event, and no further action is required.

1545 360