

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

REPORT SOURCE 1 6 0 5 0 0 0 3 4 8 7 0 6 2 4 7 8 8 0 7 1 4 7 8 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

2 | At 0500 on 6/24/78, it was noted that FNP-0-STP-12.0 had not been performed between

3 | 6/11/78 and 6/24/78. This interval of 13 days is in excess of the 7 day \pm 25% interval

4 | specified in Technical Specification 4.5.4.1. FNP-0-STP-12.0 was performed immediately

5 | and the BIT was demonstrated operable as per Technical Specification 4.5.4.1. The

6 | health and safety of the general public was not affected.

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1. Schedule B for June, 1978 incorrectly scheduled FNP-0-STP-12.0 as a 31 day interval

2. instead of the required 7 day interval. Personnel involved were notified and a review

3. of the Surveillance Schedule was performed.

349