

DUKE POWER COMPANY

ELECTRIC CENTER, BOX 33189, CHARLOTTE, N. C. 28242

L. C. DAIL
VICE PRESIDENT
DESIGN ENGINEERING

May 25, 1979

79 JUN 1 11:58

USNRC REGIONAL
ATLANTA, GA


Mr. J. P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Re: Catawba Nuclear Station
IE:II:WPA
Inspection Report: 50-473-417/75-6
Duke File: CN-1412.11-1

Dear Mr. O'Reilly:

In the subject Inspection Report, one infraction and one deficiency were identified. Enclosed are Duke Power Company's responses to these items. Duke does not consider any of the information in the referenced Inspection Report to be proprietary.

Very truly yours,



L. C. Dail
Vice President
Design Engineering

JDW/jmi

Attachment

336 226

7907190132

89050
OFFICIAL COPY

DUKE'S RESPONSE TO INFRACTION 50-413/79-06-01

This infraction concerns the failure to identify, record and evaluate the defects remaining on the concrete containment dome pour number 32. As a corrective measure, the entire exterior surface of dome pour number 32 was reinspected in accordance with the criteria established per nonconforming item report 5252. All areas requiring repair were also completed as instructed by the resolution of nonconforming item report 5252.

To avoid further noncompliance, responsible individuals have been instructed in the importance of following the instructions as detailed on nonconforming item reports.

Full compliance was achieved April 30, 1979.

DUKE'S RESPONSE TO DEFICIENCY 50-414/79-06-01

This deficiency concerns litter and debris located on a platform which partially covered Unit 2 refueling canal. The area in question was cleared of litter and debris to meet good construction site housekeeping practices as required by a Zone VI area.

To avoid further noncompliance, responsible individuals have been instructed in the importance of maintaining designated zones to the proper housekeeping requirements.

Full compliance was achieved April 10, 1979.