

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 M A P P S I 2 0 0 0 0 0 0 0 0 0 0 0 3 4 1 1 1 1 4 5
9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

ON'T
0 1 REPORT SOURCE 7 6 0 5 0 - 0 2 9 3 7 0 6 1 6 7 9 8 0 7 1 6 7 9 9
8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 On June 16, 1979 during routine surveillance testing while shutdown for
0 3 maintenance, it was discovered that the closing times for A0-203-1A and E (Inboard
0 4 MSIV) was greater than the allowable limits of the Technical Specifications.

0 5
0 6
0 7
0 8

0 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
C D 11 E 12 B 13 V A L V O P 14 Z 15 Z 16
9 10 11 12 13 18 19 20
17 LER/NO REPORT NUMBER 7 9 21 22
18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
E 18 Z 19 Z 20 Z 21 0 0 0 0 N 23 Y 24 N 25 A 5 8 5 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause of this event was changes in the characteristics of the hydraulic
1 1 operators. Both hydraulic operators were adjusted and satisfactory times
1 2 obtained prior to station startup.
1 3
1 4

1 5 FACILITY STATUS G 28 0 0 0 29 N/A 30 METHOD OF DISCOVERY B 31 Routine Surveillance 32 DISCOVERY DESCRIPTION ON
7 8 9 10 11 12 13 44 45 46 80
1 6 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36
7 8 9 10 11 44 45 80
1 7 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 N/A 38
7 8 9 10 11 12 13 80
1 8 PERSONNEL INJURIES NUMBER DESCRIPTION 41 N/A 40
7 8 9 10 11 12 80
1 9 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43 N/A 42
7 8 9 10 80
2 0 PUBLICITY ISSUED DESCRIPTION 45 N/A 44
7 8 9 10 80

NAME OF PREPARER Charles J. Mathis

PHONE: 617 746-7900

NRC USE ONLY

950 917-026