

CONTROL BLOCK: [] [] [] [] [] [] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[0] [1] [N] [C] [B] [E] [P] [2] (2) [0] [0] [-] [0] [0] [0] [0] [-] [0] [0] (3) [4] [1] [1] [1] [1] (4) [] [] (5)
8 9 LICENSE CODE 14 15 LICENSE NUMBER 26 LICENSE TYPE 30 57 CAT 58

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | While performing normal surveillance of the reactor building, the auxiliary operator

0 3 | noticed that the sample pump for the CAC-ATH-1259 drywell atmospheric monitor was

0 4 | making a loud noise.

10 The pump bearings were found to be bad so the pump was replaced with a new one from
11 stock. The pump is being added to the preventative maintenance system for checking
12 semiannually. This is considered an isolated event and no further action is required.

PERSONNEL INJURIES		NUMBER		DESCRIPTION (41)			
1	2	0	1	0	(41)	NA	415 343

8	9	11	12	80
LOSS OF OR DAMAGE TO FACILITY (43)				
TYPE		DESCRIPTION		
1	9	Z (42)	NA	7907190534

A. C. Tollison, Jr.

919-457-9521

0000-0477-9286