

VIRGINIA ELECTRIC AND POWER COMPANY  
RICHMOND, VIRGINIA 23261

July 19, 1979

Mr. Harold R. Denton, Director  
Division of Operating Reactors  
Office of Nuclear Reactor Regulation  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Serial No. 591  
PO/FHT:baw  
Docket No: 50-338  
License No. NPF-4

Dear Mr. Denton:

Failure of Solenoid Operated Valves  
to Meet IE Bulletin 79-01  
Environmental Qualification Requirements

Please refer to our letter of June 14, 1979, Serial No. 466, on the above subject. We reported the corrective action that has been taken or will be taken to correct the lack of environmental qualification of several ASCO solenoid valves used at North Anna and Surry Power Stations. Section V of that letter, Corrective Action, should be amended to state that the replacement valves for North Anna Unit 1 will be installed during the "first appropriate outage following receipt of replacements".

Very truly yours,

*C. M. Stallings*

C. M. Stallings  
Vice President-Power Supply  
and Production Operations

cc: Mr. James P. O'Reilly, Director  
Office of Inspection and Enforcement  
Region II

398 264

7907250260

Q