



ARKANSAS POWER & LIGHT COMPANY  
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

July 6, 1979

2-079-2

Mr. K. V. Seyfrit, Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Comm.  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, TX. 76011

Subject: Arkansas Nuclear One - Unit 2  
Docket No. 50-368  
License No. NPF-6  
Reportable Occurrence Report  
Nos. 50-368/79-41, 50-368/79-42  
and 50-368/79-37 Rev.1  
(File: 2-0520)

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 2 Technical Specification 6.9.1.9, we have attached the subject reports concerning non-performance of a personnel hatch seal leakage test at least once per seventy-two (72) hours when the airlock was being used for multiple entries and the turbine overspeed protection system being inoperable for less than four hours.

Also, a revision to Reportable Occurrence Report No. 50-368/79-37 is submitted to correct an error in the event description section (i.e., 2P7B should have read 2P7A).

Very truly yours,

*John M. Giff* for  
David C. Trimble  
Manager, Licensing

DCT:gp

Attachment

cc: Mr. Victor Stello, Jr., Director  
Office of Inspection and  
Enforcement  
U. S. Nuclear Regulatory Comm.  
Washington, D.C. 20555

Mr. Norman M. Haller, Director  
Office of Management and  
Program Analysis  
U. S. Nuclear Regulatory Comm.  
Washington, D. C. 20555

Mr. W. D. Johnson  
U. S. Nuclear Regulatory Comm.  
P. O. Box 2090  
Russellville, AR. 72801

MEMBER MIDDLE SOUTH UTILITIES SYSTEM

7907120 645

567 206

(4)

S