

DUKE POWER COMPANY USNRC REGION II  
ATLANTA, GEORGIA

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

79 JUN 4 9:38

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

May 30, 1979

TELEPHONE AREA 704  
373-4083


Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30302

Re: RII:JPO  
50-269  
50-270  
50-287

Dear Mr. O'Reilly:

With regard to your letter of March 30, 1979 and my letter of May 2, 1979, please find attached Duke Power Company's response to IE Bulletin 79-04 for Oconee Nuclear Station.

Very truly yours,

  
William O. Parker, Jr.

RLG:scs  
Attachment

cc: U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Division of Reactor Construction Inspection  
Washington, D. C. 20555

7907180 883

790295  
OFFICIAL COPY

DUKE POWER COMPANY  
OCONEE NUCLEAR STATION  
Response to IE Bulletin 79-04

Duke Power Company has reviewed all Seismic Category I piping systems and has determined that 1500 psi Velan check valves were installed in the 3-inch discharge line of each high pressure injection (HPI) pump of each Oconee unit. An incorrect valve weight was used in the piping analysis of these lines.

A reanalysis of the affected HPI piping has been initiated to determine if additional supports or restraints are required. The computer code SUPERPIPE is being utilized in this analysis.

A report will be submitted upon completion of this analysis, which is expected to be completed by June 29, 1979.