

D&E  
M Collins

BOSTON EDISON COMPANY

TELECOPY MESSAGE

To: 215-337-5324  
Telephone Number

Date/Time: July 16, 1979 / 0900

To: Director, Region I  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406

From: Pilgrim Nuclear Power Station  
RFD #1 Rocky Hill Road  
Plymouth, MA 02360

Subject: PROMPT REPORTABLE OCCURRENCE  
Docket Number 50-293; License DPR-35  
  
Assigned LER Number 79-022/01X-0

Event Description: On July 13, 1979, while continuing our evaluation of seismic restraints, it was discovered that two pipe supports did not meet

the original design SSE specifications. These pipe supports are on the HPCI test line downstream of the test valve and on the RHR cross tie.

Cause and Corrective Action: The cause of this event was design error.

Plant design changes requests were prepared and modifications are in progress to bring the supports up to standards.

Facility Status:

- c) Routine Startup \_\_\_\_\_
- d) Routine Shutdown \_\_\_\_\_
- e) Steady State \_\_\_\_\_
- f) Load Changing \_\_\_\_\_

0 I Thermal MW

- g) Shutdown X
- h) Refueling \_\_\_\_\_
- i) Other \_\_\_\_\_
- j) Not Applicable \_\_\_\_\_

A written follow-up report will be sent within two weeks.

NRC person notified T. Stedka

Prepared by Charles J. Mathis

**POOR ORIGINAL**

7907200 275

Mail (2) copies to:

Director  
Office of Management Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

A002  
S/10

462 359