

7900803L

TELEPHONE REPORT

FACILITY: V. Summer

DOCKET #: 50-395

DATE: 7/19/79

TIME: 11:00 a.m.

LIC. OCC. #: _____

SUBJECT: Condensate Storage Tank Leakage

DESCRIPTION OF OCCURRENCE: Mark Whitaker, Dave Moore, and Ron Clang stated

that the subject tank was found to be leaking (residual water). A

preliminary examination revealed that the bottom plates are now buckled and weld failures are allowing water leakage. The tank is mounted on a concrete slab with a sand buffer in-between. An upward movement of a drain pipe is thought to have caused the plate buckling. Pipe movement may have been caused by a shift in the sand buffer or a construction vehicle may have backed into the tank. Report due in 30 days (August 18, 1979)

R.D.B. / 24
SIGNATURE

POOR ORIGINAL

7908030371

6019
S 1/0481 197
790238