

Detroit

2000 Second Avenue  
Detroit, Michigan 48226  
(313) 237-8000

July 25, 1979  
EF2-50,107

Mr. James G. Keppler  
Regional Director  
Directorate of Regulatory Operations  
Region III  
U. S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Subject: 10CFR50.55(e) Deficiency Report on Handling Damage  
to Core Spray Pump Motor

References: (a) Reporting of Potential 10CFR50.55(e) Deficiency  
to Mr. H. S. Phillips on February 23, 1979  
(b) Interim Status Report EF2-46,125 dated March 22,  
1979


Dear Mr. Keppler:

Pursuant to the provisions of 10CFR50.55(e) (3), this interim report is being filed as an official follow-up to reference (a) concerning handling damage to the Core Spray Pump Motor identified as E21-01-C001-D.

The motor was sent to General Electric Company's Manufacturing Division, San Jose, California. Disassembly and inspection have been performed. Edison Engineering, in conjunction with General Electric representatives, are presently evaluating the extent of damage and determining the necessary repairs.

A final report will be issued if the resulting damage is considered significant enough to be classified as a reportable deficiency. If we determine it not to be reportable under 50.55(e), we will notify your office.

Sincerely yours,



W. J. Fahrner  
Project Manager  
Enrico Fermi II

cc: Mr. John G. Davis  
Acting Director  
Office of Inspection and Enforcement  
Division of Reactor Inspection Programs  
U.S. Nuclear Regulatory Commission  
Washington D.C. 20555

B019  
S 1/0

7908080515 509 136