



July 9, 1979
L-79-184

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: RII:JPO
50-250, 50-251
IE Bulletin 79-11

Twelve of the DB-50 overcurrent trip devices (with dashpots) referenced in the subject Bulletin are in use at Turkey Point Units 3 and 4. The devices are installed on the CRDM MG set output breakers, which are not part of a safety related system.

In addition, DB-50 overcurrent trip devices are used for reactor trip and bypass functions. These devices do not have dashpots, therefore, they are not affected by the Bulletin.

This completes our action in response to IE Bulletin 79-11.

Very truly yours,

Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU/MAS/paf

Attachment

cc: Robert Lowenstein, Esquire

7903090 541

590 001

ORIGINAL COPY