

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 M N P I N 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
 7 8 9 14 15 25 26 30 37 CAT 38

CON'T

0 1 REPORT SOURCE L 6 0 5 0 0 0 2 8 2 7 0 6 0 9 7 9 8 0 7 0 9 7 9 9
 7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During cooldown operations, MV-32196, Pressurizer Power-Operated Relief Isolation,
 0 3 failed to close on demand. Not repetitive. No effect on public health and
 0 4 safety. After replacement of a torque switch the valve operated properly.
 0 5
 0 6
 0 7
 0 8

0 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
 C A 11 E 12 A 13 I N S T R U 14 S 15 Z 16
 7 8 9 10 11 12 13 18 19 20
 17 LER/RO REPORT NUMBER EVENT YEAR 7 9 21 22
 0 2 0 27 SEQUENTIAL REPORT NO. 0 3 28 OCCURRENCE CODE L 30 REPORT TYPE
 33 ACTION TAKEN 18 Z 34 FUTURE ACTION 19 Z 35 EFFECT ON PLANT 20 Z 36 SHUTDOWN METHOD 21
 0 0 0 0 37 HOURS 22 N 40 ATTACHMENT SUBMITTED 23 Y 42 NPD-4 FORM SUB. 24 N 43 PRIME COMP. SUPPLIER 25
 L 2 0 0 44 COMPONENT MANUFACTURER 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Failure of torque switch in Limitorque SMB-00 operator. Switch was replaced.
 1 1
 1 2
 1 3
 1 4

1 5 FACILITY STATUS G 28 0 0 0 0 29 11 OTHER STATUS 30 N/A 44 METHOD OF DISCOVERY A 31 Operator observation during stroke test 45
 7 8 9 10 12 11 44 45 46 80

1 6 ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 NA 44 AMOUNT OF ACTIVITY 35 NA 45 LOCATION OF RELEASE 36

1 7 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 0 0 0 37 Z 38 NA 40
 7 8 9 11 12 13 80

1 8 PERSONNEL INJURIES NUMBER DESCRIPTION 41 0 0 0 40 NA 42
 7 8 9 11 12 80

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43 Z 42 NA 44
 7 8 9 10 80

2 0 PUBLICITY ISSUED DESCRIPTION 45 N 44 NA 46
 7 8 9 10 80

NAME OF PREPARER A. A. Hunstad

PHONE 612-388-4767

361 199

7907180473 S

NRC USE ONLY