

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	C	B	E	P	2	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
7	8	3					14	15										25	26					30		57	CAT	58
LICENCEE CODE				LICENSE NUMBER										LICENSE TYPE														

0	1	REPORT SOURCE		L	6	0	5	0	-	0	3	2	4	7	0	6	1	9	7	9	8	0	7	1	2	7	9	9		
7	8			60	61	DOCILET NUMBER										68	69	EVENT DATE					74	75	REPORT DATE					80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During normal plant operation, a clearance was given to the mechanics to uncouple

03 12B RHR service water pump for an alignment check. The mechanics uncoupled 2A RHR

04 service water pump by mistake, making both loops of RHR service water inoperable for

06 (Technical Specification 3.7.1.1, 6.9.1.9b)

1 0 When the mistake was discovered, the 2A pump was immediately recoupled and tested to

insure operability. This event was discussed with all the mechanic crews, noting that

[1] [2] these pumps are safety related and clearly marked. A memorandum will be issued to

[] [3] plant management requiring that future clearances be issued only to personnel who have

1 4 had training in the clearance procedure. The individuals involved in this (Con't)

8 9 80

FACILITY STATUS		% POWER		OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION			
1	5	E	28	088	23	NA	A	31	Mechanic Observation

PERSONNEL EXPENDITURES									
MONTH			YEAR		DESCRIPTION				
1	2	3	4	5	6	7	8	9	10
1	7	0	0	0	37	2	30	NA	

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	2	0	0	0	(49) NA

4/26 200

1		9		Z		42		NA		7907160408	
8		9		10		11		12		13	

A. C. Tollison, Jr.

919-457-9521

LER CONTINUATION -- RO# 2-79-050

Facility: BSEP Unit No. 2

Event Date: 6-19-79

incident were counselled on the serious nature of events of this type.