

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONT

0	1
---	---

REPORT SOURCE

L	6	0	5	0	0	0	3	6	6	7	0	7	1	2	7	9	8	0	8	0	3	7	9	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

POCKET NUMBER

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

[illegible]

7 8 9 METHOD OF

[illegible]

COPIES OF INFORMATION TO FACILITY TYPE DESCRIPTION (43) 190010

R. T. Nix

PHONE: 912-367-7731

NRC USE ONLY

Georgia Power Company
P. O. Box 442
Baxley, Georgia 31513

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

(Cont.)

on the airlock interior, (b) replacing outer door with one containing a window, (c) installing a local alarm to indicate to the personnel entering or exiting the airlock that the secondary containment has been broken. (e) installing a positive door locking system which requires unlatching as part of opening the door. All of the secondary containment airlocks will be considered in the application of any functional improvements considered to help prevent further violations of this type.

618065