

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 F L Q R P 3 0 0 - 0 0 0 0 0 - 0 0 4 1 1 1 1 - - 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

01 L 0 5 0 - 0 3 0 2 0 6 0 4 7 9 0 6 2 5 7 9 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

02 It was determined at 1300 on 4 June 1979 that AHF-14D had failed on 25 May
03 1979, creating an event contrary to T.S. 3.9.12. No effect upon public
04 health and safety as redundant air handling fans AHF-14A & 14C were available
05 and operable. This is the seventh (7th) occurrence reported for AHF-14D.
06 Reference LER's 78-30,43, 64, 65, 66, and 70.
07
08
09

09 A A E A B L O W E R Z Z
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

17 LER NO REPORT NUMBER 7 9 1 0 5 6 1 0 3 L 0
21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

ACTION TAKEN B X Z Z 0 0 0 0 Y N A J 1 2 7
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

10 The cause of this event is unknown. The fan was repaired and returned to ser-
11 vice at 0900 on 19 June 1979. Request for Engineering Information 78-12-4 has
12 been initiated to evaluate this problem and provide possible solutions to
13 prevent recurrence. Corrective action to be based on the results of this
14 evaluation.
15
16
17
18
19

15 H 0 0 0 NA B Operator observation
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

16 Z Z NA NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

17 0 0 0 Z NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

18 0 0 0 NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

19 Z NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

20 N NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

NAME OF PREPARED J. Cooper, Jr.

PHONE (904) 795-6486

(SEE ATTACHED SUPPLEMENTARY INFORMATION SHEET)

285 045

7907030486

S

SUPPLEMENTARY INFORMATION

Report No.: 50-302/79-056/03L-0

Facility: Crystal River Unit #3

Report Date: 25 June 1979

Occurrence Date: 25 May 1979 (Determined at plant 4 June 1979)

Identification of Occurrence:

Auxiliary Building ventilation system inoperable contrary to Technical Specification 3.9.12.

Conditions Prior to Occurrence:

Mode 5 cold shutdown.

Description of Occurrence:

It was determined at 1300 on 4 June 1979 that AHF-14D had failed on 25 May 1979. Subsequent investigation revealed that the fan motor and blading were damaged. The fan motor was repaired and the blading was replaced. AHF-14D was returned to service at 0900 on 19 June 1979.

Designation of Apparent Cause:

The cause of this event is unknown.

Analysis of Occurrence:

No effect upon public health and safety as redundant air handling fans AHF-14A and AHF-14C were available and operable.

Corrective Action:

Request for Engineering Information 78-12-4 has been initiated to evaluate this problem and provide possible solutions to prevent recurrence. Further corrective action to be based on the results of this evaluation.

Failure Data:

This is the seventh (7th) occurrence reported for AHF-14D. Reference LER's 78-30, 43, 64, 65, 66, 70.

/rc

285 046