

79047

Headquarters

TELEPHONE REPORT

USNRC PRC
ATLANTA

19 AUG 3 P 1: 53

FACILITY: Sequoyah

DOCKET #: 50-327

DATE: 8/2/79

TIME: 4:00 pm

LIC. OCC. #: NCR EEB 79-13

SUBJECT: Arcing across underfrequency relay contacts

DESCRIPTION OF OCCURRENCE: ^{Chattering of} ~~Potential~~ CDR - ~~Arcing across~~ Underfrequency

relay contacts caused the auxiliary relay to chatter. Chattering delays the reactor trip and the reactor cooling pump trip signals. A relay change is being made to correct the problem in Unit 1. A design change has been initiated to change from DC to AC for ^{Sequoyah} Unit 2 and ^{implemented} Watts Bar Unit 1 & 2. The design change will be made on Unit 1 during ^A the first refueling outage. ^{A Sequoyah}

Report due 8/31/79

J. J. J. / J. J. J.
SIGNATURE

POOR ORIGINAL

79081506320

692256

3019
5/10
790417