



Consumers
Power
Company

Stephen H. Howell
Senior Vice President

General Offices: 1945 West Parnall Road, Jackson, Michigan 49201 • (517) 788-0453

August 10, 1979
Howe-220-79

Mr J G Keppler, Regional Director
Office of Inspection and Enforcement
US Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

POOR ORIGINAL

MIDLAND NUCLEAR PLANT -
UNIT NO 1, DOCKET NO 50-329
UNIT NO 2, DOCKET NO 50-330
STATES TERMINAL BLOCKS, CRACKED DISCONNECT LINKS

In accordance with the requirements of 10 CFR 50.55(e), this letter constitutes an interim report on the status of discrepant terminal block disconnect links.

The attachments to this letter provide a description of the discrepancy, safety implication, investigation and planned corrective actions.

Another report, either interim or final, will be sent on or before October 26, 1979.

Belmont for SH Howell

- Attachments: 1. Quality Assurance Program, Management Corrective Action Report, MCAR-1, Report 32, dated July 20, 1979
2. MCAR-32, Interim Report #1, dated August 6, 1979

CC: Director of Office of Inspection and Enforcement
Att: Mr Victor Stello, USNRC (15)

Director of Office of Management
Information and Program Control, USNRC (1)

837 001

7908210421 5