

No. 3-79-22/3L-0

This LER refers to the failure of pressure switch PS-3-10-119D which senses high drywell pressure. The governing Technical Specifications are 3.2.B and 6.9.2.b(2).

## 1. CENSEE EVENT REPORT

790821053/5