

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

08 _____

(17) LER/RO REPORT NUMBER
 EVENT YEAR
 REPORT NO.
 OCCURRENCE CODE
 REASON TYPE
 NO.

ACTION FUTURE EFFECT SHUTDOWN ATTACHMENT NPRO-4 PRIME COMP. COMPONENT
TAKEN ACTION ON PLANT METHOD METHOD SUBMITTED FORM SUB. SUPPLIER MANUFACTURER
C 18 Z 19 Z 20 Z 21 0 0 0 22 Y 23 Y 24 L 25 K 1 2 0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 5 FACILITY STATUS (28) 0 POWER 9 (29) OTHER STATUS (30) METHOD OF DISCOVERY (31) DISCOVERY DESCRIPTION (32)
7 8 9 E 10 11 12 NA 13 44 45 46 Operator observed an alarm 47 48 49

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) NA LOCATION OF RELEASE (36)

PERSONNEL EXPOSURES										
NUMBER			TYPE	DESCRIPTION (39)						
1	2	0	0	0	(37)	Z	(38)	NA		

PERSONNEL INJURIES		DESCRIPTION (41)	
NUMBER			
0	0	0	NA

7		8		9		11		12		80	
LOSS OF OR DAMAGE TO FACILITY										(43)	
TYPE DESCRIPTION											
1		9		7		(42)		NA		928327	

PUBLICITY		NRC USE ONLY	
ISSUED	DESCRIPTION		
AT 14	45		

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----

NAME OF PREPARER

PHONE

7909110

LER SUPPLEMENTAL INFORMATION

BFRO-50- 259 / 7915 Technical Specification Involved T.S. 3.11.C-1 and 2

Reported Under Technical Specification T. S. 6.7.2.b.2

Date of Occurrence 8/5/79 Time of Occurrence 0450 Unit 1

Identification and Description of Occurrence:

A smoke detector for the auxiliary instrument room alarmed and would not clear. The alarm would have masked signals from detectors which are required to be operational by T. S. 3.11.C.1.

Conditions Prior to Occurrence:

The unit was under normal operating conditions with power output of 89%. All smoke detectors were operable and all alarms clear.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

A fire watch was established.

Apparent Cause of Occurrence:

Increased detector sensitivity due to normal aging.

Analysis of Occurrence:

NA

Corrective Action:

Detector was replaced.

Failure Data: Similar events: 296/7722, 259/7801, 259/7809, 296/7809, 296/7817, 296/7823, 296/7826, 296/7828.

*Retention: Period - Lifetime, Responsibility - Administrative Supervisor

*Revision:

928328