



ARKANSAS POWER & LIGHT COMPANY  
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

September 12, 1979

2-099-8

K. V. Seyfrit, Director  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, TX 76011

Subject: Arkansas Nuclear One-Unit 2  
Docket No. 50-368  
License No. NPF-6  
Reportable Occurrence Report  
Nos. 50-368/79-074; 50-368/79-075  
(File: 2-0520)

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 2 Technical Specification 6.9.1.9., we have attached the subject reports concerning the "A" CPC trips being bypassed to allow the change out of the RSPT power supplies which were causing erroneous position indication inputs (50-368/79-074); and the tripping of the "B" CPC channel caused by an inaccurate output indication from the data link in CEAC #1 (50-368/79-075).

Very truly yours,

*David C. Trimble*

David C. Trimble  
Manager Licensing

DCT:REI:gp

Attachment

cc: Mr. Victor Stello, Jr, Director  
Office of Inspection and  
Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Mr. Norman Haller, Director  
Office of Management and  
Program Analysis  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Mr. W. D. Johnson  
U. S. Nuclear Regulatory Commission  
P. O. Box 2090  
Russellville, AR. 72801

364359

7909180490