

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CON'T
0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES ⑩

0 2 During inspection of 11 and 12 diesel generator pipe hangers per IE Bulletin
0 3 79-14, discovered that the air start system hangers were not built to meet
0 4 seismic requirements. To meet T.S. 3.8.1.1 started D/Gs within one hour and
0 5 thus they no longer relied on the air start system for operability. This is
0 6 not a repetitive occurrence.

0 7
0 8

0 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
E E ⑪ B ⑫ A ⑬ P I P E X X ⑭ A ⑮ Z ⑯

⑰ LER NO. REPORT NUMBER ⑱ EVENT YEAR ⑲ SEQUENTIAL REPORT NO. ⑳ OCCURRENCE CODE ㉑ REPORT TYPE ㉒ REVISION NO.
7 9 0 4 7 0 1 X 0

ACTION TAKEN ㉓ FUTURE ACTION ㉔ EFFECT ON PLANT ㉕ SHUTDOWN METHOD ㉖ HOURS ㉗ ATTACHMENT SUBMITTED ㉘ NRPD-4 FORM SUB. ㉙ PRIME COMP. SUPPLIER ㉚ COMPONENT MANUFACTURER
C ⑰ Z ⑱ Z ⑲ Z ⑳ 0 0 0 0 N ㉓ N ㉔ A ㉕ X 9 9 9 ㉖

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS ⑳

1 0 Hangers meeting seismic requirements will be installed in about 5 to 7 days.

1 1
1 2
1 3
1 4

POOR ORIGINAL

1 5 FACILITY STATUS ㉗ N-POWER ㉘ OTHER STATUS ㉙ METHOD OF DISCOVERY ㉚ DISCOVERY DESCRIPTION ㉛
E ㉗ 0 5 0 ㉘ N/A ㉙ I D ㉚ Visual Inspection ㉛

1 6 ACTIV. CONTENT ㉜ RELEASED OR RELEASE ㉝ AMOUNT OF ACTIVITY ㉞ LOCATION OF RELEASE ㉟
Z ㉜ Z ㉝ N/A ㉞ N/A ㉟

1 7 PERSONNEL EXPOSURES ㊱ NUMBER ㊲ TYPE ㊳ DESCRIPTION ㊴
0 0 0 ㊱ Z ㊲ N/A ㊳

1 8 PERSONNEL INJURIES ㊵ NUMBER ㊶ DESCRIPTION ㊷
0 0 0 ㊵ N/A ㊶

1 9 LOSS OF OR DAMAGE TO FACILITY ㊸ TYPE ㊹ DESCRIPTION ㊺
E ㊸ N/A ㊹

2 0 FACILITY STATUS ㊻ N-POWER ㊼ OTHER STATUS ㊽ METHOD OF DISCOVERY ㊾ DISCOVERY DESCRIPTION ㊿

App 2
5/11

NAME OF OPERATOR L. B. Russell

PHONE (301) 234-7921
7909250422 1026 353