

**LICENSEE EVENT REPORT**

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7 8 3 14 15 25 26 30 37 38 57 58

0 1 M D C C N 1 2 0 0 - 0 0 0 0 0 0 1 - 0 0 3 4 1 1 1 1 1 4 5

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T

REPORT SOURCE: 01 L 6 0 5 0 0 0 3 1 7 7 0 8 2 7 7 9 8 0 9 2 6 7 9 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | The auxiliary high pressure safety injection (HPSI) header 12 and 13 charging  
0 3 | pumps were placed out of service from 1857 to 0345 on 8/27/79 (T.S.3.5.2 and  
0 4 | 3.1.2.4) in order to repair a cracked weld on the charging header (T.S.6.9.1.9).  
0 5 | The normal HPSI header and 11 charging pump which was lined-up to the auxiliary  
0 6 | HPSI header remained operable during the event. This is not a repetitive  
0 7 | occurrence.

08 7 8 9 80

SYSTEM CODE P C		CAUSE CODE B		CAUSE SUBCODE C		COMPONENT CODE P I P E X X				COMP. SUBCODE A		VALVE SUBCODE Z	
7	8	9	10	11	12	13	14	15	16	17	18	19	20
LER/RO REPORT NUMBER 7 9		EVENT YEAR 7 9		SEQUENTIAL REPORT NO. 0 4 6		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 0			
21	22	23	24	25	26	27	28	29	30	31	32		
ACTION TAKEN A		FUTURE ACTION Z		EFFECT ON PLANT A		SHUTDOWN METHOD A		HOURS 0 0 1 6		ATTACHMENT SUBMITTED N			
33	34	35	36	37	38	39	40	41	42	43	44		
PRIME COMP. SUPPLIER A		COMPONENT MANUFACTURER S 0 3 0											
45	46	47	48										

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The action statements were voluntarily entered to repair a cracked weld on a  
1 1 reducer for the sample line pipe. The reducer was removed and replaced. Lack  
1 2 of fusion in the weld appears to be the cause of the crack. No further corrective  
1 3 action is required as the weld was made during initial construction.

1	4		80
7	8	9	

FACILITY STATUS (28) 1 5 8 9 E  
% POWER (29) 0 8 5  
OTHER STATUS (30) NA  
METHOD OF DISCOVERY (31) A  
DISCOVERY DESCRIPTION (32) NA

ACTIVITY CONTENT  
RELEASED OF RELEASE

1 6 0 33 0 34

7 8 9 10 11

AMOUNT OF ACTIVITY (35)

NA

44

LOCATION OF RELEASE (36)

NA

45 80

PERSONNEL EXPOSURES

NUMBER		TYPE	DESCRIPTION
1	7	000	NA

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
18	000	40	NA

8		9		11		12	
TYPE		LOSS OF OR DAMAGE TO FACILITY DESCRIPTION					
1	9	Z	(42)	NA			

1060 002

7 8 9 10  
PUBLICITY  
ISSUED DESCRIPTION (45) NA 7910010405 NRC USE ONLY

NAME OF PREPARER S. M. Davis/M. J. Miernicki

PHONE: (301) 234-7942/7962