



VIRGINIA ELECTRIC AND POWER COMPANY, RICHMOND, VIRGINIA 23161

October 19, 1979

Mr. James P. O'Reilly, Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Serial No. 784A  
PSE&C/GLP:mac:wang

Docket Nos. 50-404  
50-405

Dear Mr. O'Reilly:

AUXILIARY FEEDWATER PUMP MOTOR  
CASTING DEFECT

As we indicated in our five day report, September 25, 1979, the vendor's representative was requested to inspect the motors at the North Anna site. The inspector did look the motors over and he agreed that there is a defect in the castings for these motors. The vendor has informed us that a complete evaluation of the castings will be done and that he will correct the problem such that the motors will meet the requirements for Category I system use.

We do not have a firm schedule for completion of the corrective actions as yet, but we will keep you informed as to the progress on this item. You should consider this an interim report at this time. We will submit the final resolution to this problem as it becomes available.

Very truly yours,

for Sam C. Brown, Jr.  
Senior Vice President - Power Station  
Engineering and Construction

cc: Mr. Victor Stello, Director  
Office of Inspection & Enforcement

Mr. Harold R. Denton, Director  
Office of Nuclear Reactor Regulation

1201 029

Bol  
S  
1/0

7910230 504