

CONTROL BLOCK: | | | | | | | ① (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

07

0	8		
---	---	--	--

(17) LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
 21 22 23 24 25 26 27 28 29 30 31 32
 7 9 — 0 2 4 / 0 3 L — 0

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

33 C 18 34 Z 19 35 Z 20 36 Z 21 37 0 0 0 0 40 41 N 23 42 24 43 N 25 44 B 0 6 9 47 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 NBI-PS-55D is a Barksdale Model B2T pressure switch. The switch setpoint started

1 1 to drift excessively. The switch was readjusted to the proper setpoint at the time

1 2 of occurrence and after further checks showed continued unsatisfactory performance,

1 3 the switch was replaced. Switch will be subjected to further examination.

1	4	
---	---	--

1 5 E 28 1 0 0 29 NA 30 B 31 32 Surveillance Testing

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 7 8 9 10 11

35

AMOUNT OF ACTIVITY

NA

44

45

LOCATION OF RELEASE

36

NA

80

PERSONNEL EXPOSURES					
NUMBER		TYPE	DESCRIPTION		
1	7		(37)	(38)	(39) NA
0	0	0	Z		

PERSONNEL INJURIES										
NUMBER				DESCRIPTION						
1	2	3	4	5	6	7	8	9	10	
0	0	0	0	40	NA					1277 035

1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23</																																																							

2 0 1 N (44) NA (45) 7911060 NRC USE ONLY

NAME OF REPAIRER David Phillips PHONE 402-825-3811