

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

NAME OF PREPARED S. M. Davis/P.G. Rizzo PHONE (301) 234-7942/7936

1388 131
POOR ORIGINAL

7911230

260

NRC USE ONLY

S. M. Davis/P.G. Rizzo

PHONE (301) 234-7942 / 7936

LER ATTACHMENT

LER NO. 79-38/3L
DOCKET NO. 50-318
EVENT DATE 10/22/79
REPORT DATE 11/20/79
ATTACHMENT

POOR ORIGINAL

CAUSE DESCRIPTION AND CORRECTIVE ACTION: (CONTINUED)

In normal manner, the technician had informed the Control Room Operator that he would be removing a transmitter from service prior to the event. This action helped reduce Operator response time when the event occurred. The involved technician has been instructed to use particular care in removing equipment from service.

To prevent recurrence, metal instrument number tags will be added to the transmitters in this area within Containment. Transmitter covers will also be marked with the instrument numbers. This action will be completed before the current Refueling Outage is ended.

1388 132