

TIC

JUL 13 1979
N9:15
N9800
N9800

VIRGINIA ELECTRIC AND POWER COMPANY
RICHMOND, VIRGINIA 23261

August 7, 1979

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Serial No. 426B
PO/FHT:scj
Docket Nos. 50-338
50-339
License Nos. NPF-4
CPPR-78

Subject: IE Bulletin 79-11, Amended Response

Dear Mr. O'Reilly:

In our July 13, 1979, letter, Serial 426A, we provided our response to the subject Bulletin for North Anna Units 1 and 2. We stated, in response to question four, that all 480 volt and above safety-related circuit breakers are checked to confirm overcurrent time delay protection by existing preventive maintenance procedures at least once each refueling outage. This statement is in error, as such procedures have not yet been finalized.

We are presently preparing procedures to confirm overcurrent time delay protection each refueling outage and we will have them completed in time to perform the required testing during the upcoming first refueling at North Anna Unit 1.

Very truly yours,

C. M. Stallings

C. M. Stallings
Vice President-Power Supply
and Production Operations

935071

7909100 204 SPECIAL COPY