

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | G | A | E | I | H | 1 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT NO

0 1 | 1 | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 2 | 1 | 7 | 0 | 8 | 2 | 2 | 7 | 9 | 8 | 0 | 9 | 0 | 5 | 7 | 9 | 9

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

CON'T REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | While performing procedure HNP-1-3357, Spray/Sprinkler valve checks safety related

0 3 | areas, a link in the electric fire pump start circuit was opened per procedure require

0 4 | ments making the electric fire pump inoperable. Number 3 Diesel fire pump had been

0 5 | tagged inoperable for maintenance thereby leaving only one fire pump ready in

0 6 | violation of Tech. Specs. 3.13.2.

0 7 |

0 8 |

7 8 9

0 9 | A B 11 | D 12 | Z 13 | Z Z Z Z Z Z 14 | Z 15 | Z 16

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

17 | 7 | 9 | 0 | 6 | 9 | 0 | 3 | L | 0

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.

18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 31 | 32

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NFRD-4 FORM SUB PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

G 18 Z 19 Z 20 Z 21 0 0 0 0 N 23 N 24 Z 25 Z 9 9 9 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | This event was caused by the inadequacy of procedure HNP-1-3357 in making plant

1 1 | personnel aware that the electric fire pump would be inoperable while the procedure

1 2 | was being performed. Procedure HNP-1-3357 has been revised so that it will not

1 3 | make the electric fire pump inoperable and so that plant personnel will be aware of

1 4 | the electric fire pump status while this procedure is being performed.

1 5 | G 28 | 0 | 0 | 0 | 29 | NA 30 | A 31 | Personnel Observation 32

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

1 6 | Z 33 | Z 34 | NA 35 | NA 36

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

1 7 | 0 | 0 | 0 | 37 | Z 38 | NA 39

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

1 8 | 0 | 0 | 0 | 40 | NA 41

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

PERSONNEL INJURIES NUMBER DESCRIPTION

1 9 | Z 42 | NA 43

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

2 0 | N 44 | NA 45

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

PUBLICITY ISSUED DESCRIPTION

NAME OF PREPARED

R. T. NIX

7909140354

PHONE 912-367-7781

343157

NRC USE ONLY

POOR
ORIGINAL