



October 9, 1979  
MP-2-4154

Mr. Boyce H. Grier  
Director, Region I  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

POOR ORIGINAL

Reference: Facility Operating License No. DPR-65  
Docket No. 50-336  
Reportable Occurrence 50-336/79-27/01T-0

Dear Mr. Grier:

This letter forwards Licensee Event Report 79-27/01T-0, required to be submitted within two weeks pursuant to the requirements of the Millstone Unit 2 Appendix A Technical Specifications, Section 6.9.1.8.i. The report concerns the discovery of conditions not specifically considered in the SAR or Technical Specifications that require remedial action or corrective measures to prevent the existence or development of an unsafe condition.

The initial notification was provided by telephone on September 24, 1979 and confirmed by telecopy on September 25, 1979. An additional three copies of the report are enclosed.

Yours truly,

J. F. Opeka  
Station Superintendent  
Millstone Nuclear Power Station

JFO/ECF/JOC:11m

Attachment: LER 79-27/01T-0

cc: Director, Office of Inspection and Enforcement, Washington, D.C. (40)  
Director, Office of Management Information and Program Control, Washington, D.C. (3)

1154 221

7910160

437

S