

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 F L G R P 3 00-000000-00 41111 4-5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CON'T
01 L 0 5 0 - 0 3 0 2 0 9 1 5 7 9 1 0 0 8 7 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
02 At 1620 in Mode 1, it was reported that control rod 07-07 partially dropped
03 from 41% withdrawn to 18% withdrawn. This created an event contrary to Techni-
04 cal Specification 3.1.3.1. Redundancy NA. No effect upon the plant or general
05 public. This is the fifth occurrence of this type reported. Reference LER's
06 77-34, 43, 47, 135.
07
08
09

SYSTEM CODE R B 11 CAUSE CODE X 12 CAUSE SUBCODE Z 13 COMPONENT CODE Z Z Z Z 14 COMP SUBCODE Z 15 VALVE SUBCODE Z 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

LER NO REPORT NUMBER 7 9 21 EVENT YEAR 7 9 22 SEQUENTIAL REPORT NO. 0 8 5 23 OCCURRENCE CODE 0 3 24 REPORT TYPE L 25 REVISION NO. 0 26
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

ACTION TAKEN X 33 FUTURE ACTION Z 34 EFFECT ON PLANT B 35 SHUTDOWN METHOD Z 36 HOURS 0 0 0 0 37 ATTACHMENT SUBMITTED Y 38 APPROVALS N 39 DRIVE COMP SUPPLIER Z 40 COMPONENT MANUFACTURER Z 9 9 9 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10 The cause of this event is unknown. Reactor power was reduced to 60%. Rod 07-07
11 was pulled from 10% to 25% and position was verified by zone reference at 25%.
12 Rod 07-07 was withdrawn to its group average position. No further corrective acti-
13 on deemed necessary.
14
15

FACILITY STATUS E 53 POWER 0 7 2 54 OTHER STATUS NA 55 METHOD OF DISCOVERY Operator observation 56
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

ACTIVITY CONCENTRATION Z 33 RELEASED OF RELEASE Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

PURFACILITY DESCRIPTION N 44
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

NAME OF PREPARED J. Cooper PHONE (904) 795-6486
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

(SEE ATTACHED SUPPLEMENTARY INFORMATION SHEET)

7910160 488

SUPPLEMENTARY INFORMATION

Report No.: 50-302/79-085/03L-0

Facility: Crystal River Unit #3

Report Date: 8 October 1979

Occurrence Date: 15 September 1979

Identification of Occurrence:

Control rod 07-07 greater than 6.5% (indicated position) away from group average position.

Conditions Prior to Occurrence:

Mode 1 power operation (72%)

Description of Occurrence:

At 1620 it was reported that rod 07-07 had dropped from 41% withdrawn to 18% withdrawn. This event resulted in a step drop in reactor power of 3%. Reactor power was reduced to 60%. Rod 07-07 was transferred to the auxiliary power supply and withdrawn to 25% by absolute position indication. Rod 07-07 position was verified at 25% on zone reference lamps. The rod was withdrawn to its average group position and power was returned to its normal supply.

Designation of Apparent Cause:

The cause of this event is unknown. Troubleshooting of the control rod power supply revealed no immediate cause of this event.

Analysis of Occurrence:

No effect upon the plant or general public.

Corrective Action:

No corrective action deemed necessary.

Failure Data:

This is the fifth occurrence of this type reported. Reference LER's 77-34, 43, 47, and 135.

/rc

1154 355