

LER 79-056/03L-0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

This event was caused by improper interpretation by plant personnel of which penetrations and walls fall under Technical Specifications and of procedures regarding fire barrier penetration operability which resulted in failure to initiate LCO action requirements.

The following corrective actions have been or will be taken:

1. LCO action requirements were met upon discovery of the problem.
2. Action was taken to repair inoperable penetrations.
3. Memoranda have been issued to appropriate plant personnel clarifying procedural and LCO requirements.
4. Action is being initiated to re-inspect all fire walls and associated penetrations. Results of this inspection will be reported in a revision to this LER.

1540 009