

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)80CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)80808090209080HO

—

PHONE: 912-367-7781

Georgia Power Company
Plant Edwin I. Hatch
Baxley, Georgia 31513

Reportable Occurrence Report No. 50-321/1979-074

Event Description and Probable Consequences (cont)

repetitive occurrence as last reported in LER-1-79-68.

Cause Description and Corrective Actions (cont)

to carry the full force of the pressure differential between the Reactor Building and the air lock interior. (2) Possible installation of communications inside the ventilation room. Presently none is installed. (3) The possible installation of some type of automatic door closer. Presently none is installed. This review will be conducted for all air locks of this type on both units and a follow-up report with our findings will be submitted.

1157 033