

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

OCT 3 4 50:06

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

October 1, 1979

TELEPHONE: AREA 704  
373-4083

Mr. J. P. O'Reilly, Director  
U.S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, GA 30303

Catawba Nuclear Station

II:RJH

Inspection Reports: 50-413/79-12 and 50-414/79-12

Dear Mr. O'Reilly:

In a September 24, 1979 letter, Mr. C. E. Murphy of your office confirmed our commitment to provide by this date a supplemental response concerning the above referenced Inspection Reports. Attached is our supplemental response.

Very truly yours,

*William O. Parker Jr.*

William O. Parker, Jr.

*by WAH*

ROS/sch  
Attachment



1209 319  
7910250506

790136  
OFFICIAL COPY

DUKE SUPPLEMENTAL RESPONSE TO  
DEFICIENCY 50-413 & 414/79 - 12 - 02

1. One documentation package from six separate specifications was rechecked to assure that a generic problem did not exist. All packages were acceptable and met the applicable specification requirements. Two of the packages contained typographical errors (i.e., transposed digits) which have been corrected by the supplier.
2. As a follow-up response to W. O. Parker's letter of September 10, 1979 to J. P. O'Reilly, applicable receiving inspection documentation that was placed in QC Hold and required QA Engineering and Service approval was reviewed. All documents were verified correct on September 28, 1979.

1209 320