

LICENSEE EVENT REPORT

CONTROL BLOCK:

1	2	3	4	5	6
---	---	---	---	---	---

 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	C	B	E	P	1	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4		5
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	--	---

7 8 9 14 15 25 26 30 57 CAT 58
LICENSEE CODE LICENSE NUMBER LICENSE TYPE

CON'T

0	1	L	6	0	5	0	-	0	3	2	5	7	0	9	2	6	7	9	8	1	0	2	5	7	9	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

7 8 60 61 68 69 74 75 80
REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	2
---	---

 During normal operation, the "RCIC Turbine Tripped" alarm annunciated. The operator

0	3
---	---

 found thr trip and throttle valve tripped and it would not reset from the RTGB.

0	4
---	---

 Technical Specifications 3.7.4, 6.9.1.9b

0	5
---	---

0	6
---	---

0	7
---	---

0	8
---	---

0	9	C	E	11	X	12	Z	13	V	A	L	V	O	P	14	B	15	Z	16
---	---	---	---	----	---	----	---	----	---	---	---	---	---	---	----	---	----	---	----

7 8 9 10 11 12 13 18 19 20
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

17	7	9		0	6	9		0	3	L		0
----	---	---	--	---	---	---	--	---	---	---	--	---

21 22 23 24 26 27 28 29 30 31 32
LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.

X	18	F	19	Z	20	Z	21	0	0	0	22	N	23	Y	24	N	25	T	1	4	7	26
---	----	---	----	---	----	---	----	---	---	---	----	---	----	---	----	---	----	---	---	---	---	----

33 34 35 36 37 40 41 42 43 44 47
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	0
---	---

 Upon investigation, it was found that the local mechanical trip had been tripped. The

1	1
---	---

 trip was reset and the RCIC turbine returned to service. It is believed that men work-

1	2
---	---

 ing above the turbine caused the trip either by stepping or dropping something on the

1	3
---	---

 latch. Covers are being installed over both unit's RCIC latch mechanisms to prevent

1	4
---	---

 recurrence.

1	5	E	28	0	9	4	29	NA	A	31	Operator Surveillance	32
---	---	---	----	---	---	---	----	----	---	----	-----------------------	----

7 8 9 10 12 13 44 45 46 80
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

1	6	Z	33	Z	34	NA	NA	36
---	---	---	----	---	----	----	----	----

7 8 9 10 11 44 45 80
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

1	7	0	0	0	37	Z	38	NA	39
---	---	---	---	---	----	---	----	----	----

7 8 9 11 12 13 80
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

1	8	0	0	0	40	NA	41
---	---	---	---	---	----	----	----

7 8 9 11 12 80
PERSONNEL INJURIES NUMBER DESCRIPTION

1	9	Z	42	NA	43
---	---	---	----	----	----

7 8 9 10 80
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

2	0	N	44	NA	45
---	---	---	----	----	----

7 8 9 10 80
PUBLICATION ISSUED DESCRIPTION

NAME OF PREPARER A. C. Tollison, Jr.

PHONE 919-457-9521

7910310 380

NRC USE ONLY

1245 356