

7-11

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003
Telephone (212) 460-3819

September 28, 1979

Re: Indian Point Unit No. 2
Docket No. 50-247

Mr. Boyce H. Grier, Director
Office of Inspection and Enforcement
Region I
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pa. 19406

Dear Mr. Grier:

Attachment A to this letter provides a report of actions taken in response to IE Bulletin No. 79-14 including revisions and supplements thereto through September 7, 1979. This report supplements our response of August 1, 1979.

As discussed with representatives of Region I by telephone on September 4, 1979, correcting nonconformances generally represented a shorter critical path outage effort than re-analysis of the effect of the nonconformance.

Accordingly, all inspections and corrections of nonconformances inside containment were completed prior to taking the reactor critical following the recent refueling/maintenance outage. All inspections and corrections of nonconformance outside containment were completed prior to taking the reactor above nominal zero power physics test levels (less than 5% reactor power). Concurrent inspections by Region I personnel assisted in identifying areas needing strengthening and added to increased overall effectiveness of our inspection efforts.

Should you or your staff have any questions regarding this report or our Bulletin 79-14 Program, we would be pleased to discuss them at your convenience.

Very truly yours,

William J. Cahill, Jr.
William J. Cahill, Jr.
Vice President

1243 357

7910310 436

Q

cc: Mr. Victor Stello, Jr., Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. Darrell G. Eisenhut, Acting Director
Division of Operating Reactors
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. T. Rebelowski, Resident Inspector
U.S. Nuclear Regulatory Commission
P. O. Box 38
Buchanan, N.Y. 10511

1243 358