

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

October 17, 1979

TELEPHONE: AREA 704
373-4083


Mr. J. P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, GA 30303

Re: McGuire Nuclear Station
Units 1 and 2
Docket Nos. 50-369 and 50-370
SD 369-370/79-08

Dear Mr. O'Reilly:

Significant Deficiency Report SD 369-370/79-08, transmitted by my letter of September 7, 1979, indicated that our review of the effects of seismic events on non-safety grade instrumentation and controls was not complete and that a followup report would be submitted. This review is now complete and no additional reportable deficiencies were discovered.

Very truly yours,


William O. Parker, Jr.

THH/sch



Bo19 5/10
1292 187

7911070 411